

MULTI

**POCKET DIGITAL MULTIMETER
MODEL MCD-007
INSTRUCTION MANUAL**

Thank you very much for selecting our model MCD-007 pocket digital multimeter.

This model is complex instrument and employ a very reliable mechanical/electronic design.

Before you use your new instrument, read this Instruction Manual completely and familiarize yourself thoroughly with all functions. With proper use and care, your tester will give you years of satisfactory service.

MULTI MEASURING INSTRUMENTS CO.,LTD.

Akihabara Murai Bldg. 7F, 1-26 Kanda Sakuma-cho,
Chiyoda-ku, Tokyo, 101-0025 Japan

TEL : +81-3-3251-7016 FAX : +81-3-3253-4278

Home Page : <http://www.multimic.com/>

E-mail : multi@multimic.com

SAFETY SUMMARY observe by all means

The Cautions and Warnings which appear on the following must be followed to ensure operator safety and retain the operating condition of the multimeter.

- △ **WARNING** : This symbol indicates the contents "Possibilities of the death or the serious wound can be supposed" caused from mis-operations.
- △ **CAUTION** : This symbol indicates the contents "Possibilities of the injury or only the material damage can be supposed" caused from mis-operations.
- The **CAUTIONS** and **WARNINGS** which appear on the following pages are stated to prevent the operator & other people from the dangers and their properties from the damages beforehand.

△ WARNING

POSSIBLE ELECTRICAL SHOCK

- This instrument is for the use of low voltage circuit.
- Do not make measurements of power lines carrying more than AC 250V.
(In some cases, power lines may carry voltage spikes of several times of the normal supply voltage).
- Do not make measurements, leaving battery cover removed.
- Before attempting to replace the batteries, first disconnect the test leads from any energized circuit.
- Do not handle the instrument with wet hands.
It is very dangerous, when measuring voltage is high.

POSSIBLE DAMAGE OF INSTRUMENT


- When making resistance measurement, continuity test or diode test, do not apply any voltage to the test probes. It will cause the defect.
- Confirm the position of rotary switch before measurement.
- Keep storage this instrument in cool and clean place.
- For cleaning of this instrument, do not apply chemicals such as thinner, benzine, etc.

GENERAL SPECIFICATIONS

Measuring Method	: Dual integration method
Measuring Function	: DC Voltage, AC Voltage, Resistance, Continuity Check, Diode Test with Data Hold & Auto Power Off functions.
Display	: LCD, max. reading of 3200 with bar graph
Polarity	: Automatic (−) negative indication
Over Range Indication	: "OL" mark on LCD readout
Low Battery Indication	: "B" mark is displayed when the battery voltage drops below operating voltage
Sampling	: 2 times/second
Operating Temperature	: 0~40°C, < 80%RH (non-condensing)
Storage Temperature	: −20~60°C, < 70%RH (non-condensing)
Power Supply	: LR-44 x 2
Power Consumption	: Approx. 5mW
Size & Weight	: 60(H)x110(W)x9.5(D)mm, approx. 60g
Accessories	: Book Type Cover Case1, Instruction Manual 1 Battery 2

NAME & EXPLANATION OF EACH PART

- ① ROTARY SWITCH : Power On/Off, Measuring Ranges for DCV, ACV, Resistance, Diode Test and Continuity Check.
- ② FUNCTION KEY : When the position of rotary switch is at Ω . ·))) \rightarrow +, can change from Ω . / ·))) / \rightarrow + by turns.
- ③ DATA HOLD KEY : By pressing this key, the display value will be hold (DH sign will appear) and it will be released by pressing once again. (DH sign will disappear).
- ④ DISPLAY : LCD display for measuring value, annunciator, battery sign, etc.
- ⑤ TEST LEADS : Red is for \oplus polarity and Black is for \ominus .
- ⑥ BATTERY COMPARTMENT (Rear Side)



MEASURING RANGES & ACCURACY (23°C ± 5°C, < 80%RH non-condensing)


Function	Range	Accuracy	Input Impedance	Max. Input Voltage
DCV	320.0mV	$\pm(1.3\%rdg \pm 3dgt)$	>1000M Ω	AC/DC 500Vrms
	3.200V	$\pm(0.7\%rdg \pm 3dgt)$	approx. 11M Ω	
	32.00V	$\pm(1.3\%rdg \pm 3dgt)$	approx. 10M Ω	
	320.0V 500V			
ACV (50/60Hz)	3.200V	$\pm(2.3\%rdg \pm 6dgt)$	approx. 11M Ω	AC/DC 500Vrms
	32.00V		approx. 10M Ω	
	320.0V			
	500V			

Function	Range	Accuracy	Testing Current	Max. Input Protection
OHM	320.0 Ω	$\pm(2\%rdg \pm 5dgt)$	<0.7mA	500Vrms
	3.200k Ω		<0.13mA	
	32.00k Ω		<13 μ A	
	320.0k Ω	$\pm(2\%rdg \pm 3dgt)$	<1.3 μ A	
	3.200M Ω		<0.13 μ A	
	32.00M Ω			
Diode Test	3.200V	$\pm(10\%rdg \pm 3dgt)$	approx.. 0.7mA	500Vrms
Continuity Check	320.0 Ω	Continuity Beeper, <approx. 20 Ω	approx.. 0.7mA	500Vrms

MEASURING METHOD

1. DC VOLTAGE (DCV)


- 1) Set the position of rotary switch from OFF to DCV (⎓ sign will be displayed).
- 2) According to the drawings, red test lead contact to \oplus polarity battery etc. and black one to \ominus .



- 3) Read the voltage value on the display. (Can measure up to 500V automatically).

2. AC VOLTAGE (ACV)

- 1) Set the rotary switch position to V and press once the select key to chose 「 \sim 」.
- 2) According to the drawings, insert the test leads to the outlet, etc. to be measured. (In case of ACV measurement, red or black test lead and polarity of \oplus or \ominus are no concern).
- 3) Read the voltage value on the display. (Can measure up to 500V automatically).



⚠ WARNING

1. Do not apply the input signal more than max. rated input voltage (500V).
2. During measurement, do not change rotary switch position.
3. Do not hold and or touch the nearer position of test leads to the tip over collar during measurement.
4. POSSIBLE ELECTRIC SHOCK
Confirm that there is no damage in the isolated wire of test leads before connecting. In case of out of order, stop the operation and repair them.
5. POSSIBLE DAMAGE & FIRE HAZARD
Connect test leads firmly, the wrong connection may cause spark.

3. RESISTANCE (Ω)

- 1) Set the rotary switch position to Ω . (·))) $\rightarrow+$ and chose Ω by select key.
- 2) According to the drawing, contact test leads to the both sides of the resistor to be measured. (It does not matter about $\oplus\ominus$ polarity).
- 3) Read the resistance value on the display. (Can measure up to 40M Ω automatically).



4. DIODE TEST ($\rightarrow+$)

- 1) Set the rotary switch position to Ω . (·))) $\rightarrow+$ and chose $\rightarrow+$ by select switch.
- 2) In case of measurement for the forward voltage, contact the test leads as in the way of drawing.


Forward Voltage

Backward

Voltage

The measuring range of general diode is between 0.4 and 0.7V.

- 3) In case of the backward voltage, contact the test leads according to the drawing. In this case, the display becomes OL generally.



5. CONTINUITY (·)))

- 1) Set the rotary switch position to Ω . (·))) $\rightarrow+$ and chose $\rightarrow+$ by select switch.
- 2) Contact the test leads to the two point to be checked for continuity.
- 3) The continuity resistance value will be displayed and the beep sounds in case of less than approx. 20 Ω .

⚠ CAUTION

POSSIBLE DAMAGE

It may cause the internal damage, if apply the voltage mistakenly at the rotary switch position of Ω . ·))) $\rightarrow +$.

REPLACEMENT OF BATTERY

⚠ WARNING

POSSIBLE ELECTRIC SHOCK & HAZARD

Do not operate with the back case removing.
Do not replace the battery at the time of measuring voltage.

⚠ CAUTION


In case of not using the instrument for a long time, keep stock with battery removing.

Power is supplied by two button type batteries (NEDA, 1166A, IEC LR 44). “ B “ appears on the LCD display when replacement is needed.

⚠ WARNING

Before attempting to replace the battery, first disconnect the test leads from any energized circuit.

- ① Disconnect the test leads from any energized circuit.
- ② Set the function switch to OFF.
- ③ Remove the battery cover screw.
- ④ Slide of battery cover and change two batteries.
- ⑤ Set the battery cover and screw.



WARRANTY

This instrument is sent out from our factory after the sufficient internal inspections but if you find any defect due to the fault in our workmanship or the original parts, please contact the dealer where you bought the instrument.

The warranty period is 12 months from the date of purchase and the instrument shall be repaired at free of charge, provided that we judge the cause of defect is obviously resulted from our responsibility.

GURANTEE REGULATIONS

1. This instrument is warranted for the operation under normal use for 12 months from the date of purchase.
2. This warranty does not cover the following defects:
 - a. Defect caused from the improper use and operation.
 - b. Defect caused from the use, operation and storage beyond the original specifications, designs and conditions.
 - c. Defect caused from the renovations or repairs done by someone else than us or our representatives.
 - d. Defect not caused from our responsibilities.